

PT

P-Touch Screen

Features

- ▷ High resolution TFT display
- ▷ All key functions of the machine are accessible
- ▷ On screen real time data
- ▷ The full range of options are programmed for "plug & play" installation of options
- ▷ Error messages display the unit that failed
- ▷ Display function for input output of PLC
- ▷ Lock out function with password protection



Ultimate Control and Information Center

The P-touch screen technology offers a graphics based interface for the operator. All main machine functions are controlled via this ultimate information center. Operation modes and sequences are selected via the touch screen. The status of the machine is monitored and the operator is informed to take action if necessary. This type of control is language independent and the graphics are displayed in four-color mode. Only graphics that are part of a selected operating mode are accessible minimizing operator errors. Every available option today is part of the software and can be activated when an option is installed at the machine at a later time. This plug and play feature makes updating the machine easy. A lock out function allows limited access by using the password feature.

The P-touch screen is directly connected to the main PLC of the machine. This enables us to directly display the machine speed and other vital information on the screen. The calendar function allows programming the start and stop of the heating elements of the machine in order to have the machine ready when the operator comes to work. Other features include a troubleshooting feature. An aggregate that fails or is not performing right is displayed on the screen saving time for maintenance. The number of pieces required for a run can be entered and tracked easily by the operator.